



CHANGE ORDER JUSTIFICATION

CHANGE ORDER
NUMBER

1

Page 1 of 1

PROJECT: Smith Island Levee Lift

PROJECT #: RR49328/WO9328

FED AID # N/A

PROJECT ENGINEER: Joshua Jones

WRITTEN JUSTIFICATION

1. DESCRIPTION OF CHANGE.

During levee excavation unforeseen subsurface conditions were encountered. This resulted in additional levee lift material (Bid Item 4) being necessary to raise the levee to the designed height. The additional material was required to meet engineering and Inter local Agreement (ILA) requirements with Diking District 5 (DD5).

2. WHAT IS REQUIRED BY CONTRACT? WHY THE CHANGE? (REFERENCE PLAN SHEETS & SPEC SECTIONS.)

- Additional 7,770.39 tons of levee lift material (Bid Item 4)
- The ILA between the county and DD5 stipulates the county will provide a one-time lift to the levee to provide the level of protection specified in the agreement.
- Unforeseen conditions discovered during levee excavation.

3. HOW IS CHANGE ORDER THE SOLUTION?

- The additional materials ensure the project adheres to all engineering and ILA requirements

4. ALTERNATIVE(S) CONSIDERED.

- Modification of the levee surface centerline was explored and not deemed viable to produce an acceptable final product.

5. REASON FOR ENTITLEMENT AND WHY IT CANNOT BE PAID UNDER EXISTING CONTRACT.

- Completion of levee lift (Bid Item 4) to necessary height resulted in an additional 7,770.39 tons of material.

6. APPROVALS: PROJECT MANAGER, TECHNICAL ADVISOR (TRAFFIC, STRUCTURAL), JURISDICTION, OTHER AGENCY.

- Change Order approval: construction manager, supervisor, manager, director, and executive.

7. TIME: INCREASE OR DECREASE WORKING DAYS.

- No change in working days. This was critical path to complete the project

8. COST: ESTABLISH OR VERIFY INCREASE OR DECREASE.

(CONTRACTOR PROPOSAL, ENGINEER'S ESTIMATE, NEGOTIATED, SUPPLIER, BID ITEM, ETC.)

- Increase of materials quantity (Bid Item 4) at the contractual rate per unit ton:
 $7,770.39 \text{ tons} \times \$23.80/\text{ton} = \$184,935.28$

ATTACH BACKUP DOCUMENTATION:

1. Estimate
2. Trucking Ticket summary
3. Ticket Tabs



FED AID # N/A

BID ITEM 4 SUMMARY

Date Weight Pay Est

8/14/2025 875.56 2

8/15/2025 576.7 2

8/18/2025 1655.61 2

8/19/2025 1575.33 2

8/20/2025 1537.66 2 6220.86

8/21/2025 908.83 3

8/22/2025 941.97 3

8/25/2025 816.89 3

8/26/2025 1556.18 3 4223.87

8/27/2025 1433.35 4 w CO

8/28/2025 1823.16 4 w CO

8/29/2025 483.34 4 w CO

9/2/2025 638.67 4 w CO

9/3/2025 1123.4 4 w CO

9/4/2025 974.41 4 w CO

9/5/2025 469.25 4 w CO

9/8/2025 423.53 4 w CO

9/9/2025 61.55 4 w CO 7430.66

17875.39 17875.39 TOTAL

10105 PER BID

7770.39 OVERAGE

\$ 184,935.28 COST OVER

GRANITE™Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.
8/28/202558727086
6:54:34AMCustomer: SCARSELLA BROS - EXEMPT
289502Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB176BD SCB176BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	101,000	45.81	50.50
Tare	39,520	17.93	19.76
Net	61,480	27.89	30.74

Scale: 1 * Manual Weight

FOB: PICK-UP

This Load: 30.74 TONS

Load No: 1

Shipped: 30.74 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727087

8/28/2025

6:58:38AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB185SD SCARCELLA BROS 185SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,500	44.68	49.25
Tare	40,100	18.19	20.05
Net	58,400	26.49	29.20
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 29.20 TONS

Load No: 2

Shipped: 59.94 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727088**
8/28/2025 7:01:59AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB181SD SCARSELLA BROS 181SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,020	44.91	49.51
Tare	40,480	18.36	20.24
Net	58,540	26.55	29.27
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 29.27 TONS

Load No: 3

Shipped: 89.21 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727089

8/28/2025

7:06:02AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,800	44.81	49.40
Tare	38,260	17.35	19.13
Net	60,540	27.46	30.27
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.27 TONS

Load No: 4

Shipped: 119.48 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727090**
8/28/2025 7:08:08AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARCELLA BROS 186SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,740	45.24	49.87
Tare	40,240	18.25	20.12
Net	59,500	26.99	29.75

Scale: 1 * Manual Weight

FOB: PICK-UP

This Load: 29.75 TONS

Load No: 5

Shipped: 149.23 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727093

8/28/2025

7:14:39AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARSELLA BROS 175BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,100	44.50	49.05
Tare	37,580	17.05	18.79
Net	60,520	27.45	30.26

Scale: 1 * Manual Weight

FOB: PICK-UP

This Load: 30.26 TONS

Load No: 6

Shipped: 179.49 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727094

8/28/2025

7:16:46AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB157SD SCARSELLA BROS 157SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,440	44.65	49.22
Tare	40,420	18.33	20.21
Net	58,020	26.32	29.01
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 29.01 TONS

Load No: 7

Shipped: 208.50 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727096

8/28/2025

7:22:37AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,200	45.45	50.10
Tare	40,100	18.19	20.05
Net	60,100	27.26	30.05
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.05 TONS

Load No: 8
Shipped: 238.55 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727097

8/28/2025

7:23:50AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB180SD SCARCELLA BROS 180SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,000	44.00	48.50
Tare	40,440	18.34	20.22
Net	56,560	25.66	28.28
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 28.28 TONS

Load No: 9

Shipped: 266.83 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727100**

8/28/2025 7:29:02AM

Correction of 58727099

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB112TT SCARSELLA BROS 112TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	104,680	47.48	52.34
Tare	44,820	20.33	22.41
Net	59,860	27.15	29.93

Scale: 1 * Manual Weight

FOB: PICK-UP

This Load: 29.93 TONS

Load No: 10

Shipped: 296.76 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727101**
8/28/2025 7:32:04AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB113TT SCARCELLA BROS 113TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	101,420	46.00	50.71
Tare	43,020	19.51	21.51
Net	58,400	26.49	29.20

Scale: 1 * Manual Weight

FOB: PICK-UP

This Load: 29.20 TONS

Load No: 11

Shipped: 325.96 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727103

8/28/2025

8:18:03AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,180	44.99	49.59
Tare	37,500	17.01	18.75
Net	61,680	27.98	30.84
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.84 TONS

Load No: 12

Shipped: 356.80 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727105

8/28/2025

8:25:09AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB176BD SCB176BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,720	44.78	49.36
Tare	39,520	17.93	19.76
Net	59,200	26.85	29.60
Scale: 1 * Manual P. T.			

Comments:

FOB: PICK-UP

This Load: 29.60 TONS

Load No: 13

Shipped: 386.40 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727106**
8/28/2025 8:26:52AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB185SD SCARCELLA BROS 185SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,800	44.36	48.90
Tare	40,100	18.19	20.05
Net	57,700	26.17	28.85

Comments:

Scale: 1 * Manual P. T.

This Load: 28.85 TONS

Load No: 14

Shipped: 415.25 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727108**

8/28/2025 8:39:21AM

Correction of 58727107

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB184BD SCARSELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,680	44.76	49.34
Tare	38,260	17.35	19.13
Net	60,420	27.41	30.21
Scale: 1 * Manual P. T			

FOB: PICK-UP

This Load: 30.21 TONS

Load No: 15

Shipped: 445.46 TONS

Comments:

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727109**
8/28/2025 8:39:52AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB181SD SCARCELLA BROS 181SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,280	45.03	49.64
Tare	40,480	18.36	20.24
Net	58,800	26.67	29.40
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.40 TONS

Load No: 16

Shipped: 474.86 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727110

8/28/2025

8:41:37AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARSELLA BROS 186SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,200	44.54	49.10
Tare	40,240	18.25	20.12
Net	57,960	26.29	28.98
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 28.98 TONS

Load No: 17

Shipped: 503.84 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727111

8/28/2025

8:44:39AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB175BD SCARSELLA BROS 175BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,620	44.28	48.81
Tare	37,580	17.05	18.79
Net	60,040	27.23	30.02

Scale: 1 * Manual P.T.

FOB: PICK-UP

This Load: 30.02 TONS

Load No: 18

Shipped: 533.86 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727113**

8/28/2025 8:46:34AM

Correction of 58727112

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB157SD SCARSELLA BROS 157SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,320	45.05	49.66
Tare	40,420	18.33	20.21
Net	58,900	26.72	29.45
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.45 TONS

Load No: 19

Shipped: 563.31 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727114

8/28/2025

8:48:37AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,340	45.06	49.67
Tare	40,100	18.19	20.05
Net	59,240	26.87	29.62
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.62 TONS

Load No: 20

Shipped: 592.93 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727115

8/28/2025

8:51:09AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB180SD SCARCELLA BROS 180SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,600	45.18	49.80
Tare	40,440	18.34	20.22
Net	59,160	26.83	29.58
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.58 TONS

Load No: 21

Shipped: 622.51 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727119

8/28/2025

9:05:15AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB112TT SCARSELLA BROS 112TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	104,780	47.53	52.39
Tare	44,820	20.33	22.41
Net	59,960	27.20	29.98
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.98 TONS

Load No: 22

Shipped: 652.49 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727120

8/28/2025

9:31:08AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB113TT SCARSELLA BROS 113TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	102,320	46.41	51.16
Tare	43,020	19.51	21.51
Net	59,300	26.90	29.65
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.65 TONS

Load No: 23

Shipped: 682.14 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727125

8/28/2025

9:49:36AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	95,800	43.45	47.90
Tare	37,500	17.01	18.75
Net	58,300	26.44	29.15
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.15 TONS

Load No: 24

Shipped: 711.29 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727126

8/28/2025

9:52:58AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB176BD SCB176BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,980	45.80	50.49
Tare	39,520	17.93	19.76
Net	61,460	27.88	30.73
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.73 TONS

Load No: 25

Shipped: 742.02 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727127**
8/28/2025 9:54:28AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB185SD SCARSELLA BROS 185SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,500	45.13	49.75
Tare	40,100	18.19	20.05
Net	59,400	26.94	29.70
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.70 TONS

Load No: 26

Shipped: 771.72 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727131**
8/28/2025 10:07:17AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB181SD SCARCELLA BROS 181SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,480	45.12	49.74
Tare	40,480	18.36	20.24
Net	59,000	26.76	29.50
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.50 TONS

Load No: 27

Shipped: 801.22 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727132**
8/28/2025 10:08:32AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARCELLA BROS 186SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,180	44.53	49.09
Tare	40,240	18.25	20.12
Net	57,940	26.28	28.97
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 28.97 TONS

Load No: 28

Shipped: 830.19 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727133**
8/28/2025 10:12:54AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARSELLA BROS 175BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,180	44.99	49.59
Tare	37,580	17.05	18.79
Net	61,600	27.94	30.80
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.80 TONS

Load No: 29

Shipped: 860.99 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727136**
8/28/2025 10:21:37AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,200	44.54	49.10
Tare	40,100	18.19	20.05
Net	58,100	26.35	29.05

Scale: 1 * Manual P. T.

FOB: PICK-UP

This Load: 29.05 TONS

Load No: 30

Shipped: 890.04 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727137

8/28/2025

10:24:05AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB157SD SCARCELLA BROS 157SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,640	45.20	49.82
Tare	40,420	18.33	20.21
Net	59,220	26.86	29.61
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.61 TONS

Load No: 31

Shipped: 919.65 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727138**
8/28/2025 10:26:39AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB180SD SCARCELLA BROS 180SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,220	45.01	49.61
Tare	40,440	18.34	20.22
Net	58,780	26.66	29.39

Comments:

Scale: 1 * Manual P. T.

FOB: PICK-UP

This Load: 29.39 TONS

Load No: 32

Shipped: 949.04 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. 58727139
8/28/2025 10:29:06AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	102,380	46.44	51.19
Tare	38,260	17.35	19.13
Net	64,120	29.08	32.06

Scale: 1 * Manual P. T.

FOB: PICK-UP

This Load: 32.06 TONS

Load No: 33

Shipped: 981.10 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727143**
8/28/2025 10:42:34AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB112TT SCARCELLA BROS 112TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	103,880	47.12	51.94
Tare	44,820	20.33	22.41
Net	59,060	26.79	29.53
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.53 TONS

Load No: 34

Shipped: 1,010.63 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727145**
8/28/2025 11:09:38AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB97TT SCB97TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,520	44.69	49.26
Tare	39,940	18.12	19.97
Net	58,580	26.57	29.29
Scale: 1			

FOB: PICK-UP

This Load: 29.29 TONS

Load No: 35

Shipped: 1,039.92 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727146**
8/28/2025 11:11:09AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB113TT SCARCELLA BROS 113TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	104,480	47.39	52.24
Tare	43,020	19.51	21.51
Net	61,460	27.88	30.73
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.73 TONS

Load No: 36

Shipped: 1,070.65 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. 58727148
8/28/2025 11:24:16AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB176BD SCB176BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,820	45.73	50.41
Tare	39,520	17.93	19.76
Net	61,300	27.81	30.65
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.65 TONS

Load No: 37

Shipped: 1,101.30 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727149**
8/28/2025 11:25:24AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB185SD SCARCELLA BROS 185SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,720	45.23	49.86
Tare	40,100	18.19	20.05
Net	59,620	27.04	29.81

Scale: 1 * Manual P. T.

FOB: PICK-UP

This Load: 29.81 TONS

Load No: 38

Shipped: 1,131.11 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. 58727151
8/28/2025 11:32:23AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB181SD SCARCELLA BROS 181SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,980	45.35	49.99
Tare	40,480	18.36	20.24
Net	59,500	26.99	29.75
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.75 TONS

Load No: 39

Shipped: 1,160.86 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727152**
8/28/2025 11:35:14AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARCELLA BROS 186SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	102,100	46.31	51.05
Tare	40,240	18.25	20.12
Net	61,860	28.06	30.93
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.93 TONS

Load No: 40

Shipped: 1,191.79 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727154**
8/28/2025 11:42:10AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,320	44.60	49.16
Tare	40,100	18.19	20.05
Net	58,220	26.41	29.11

Scale: 1 * Manual P.T.

FOB: PICK-UP

This Load: 29.11 TONS

Load No: 41
Shipped: 1,220.90 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COMMSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. 58727156
8/28/2025 11:48:39AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB180SD SCARCELLA BROS 180SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	96,600	43.82	48.30
Tare	40,440	18.34	20.22
Net	56,160	25.47	28.08

Comments:

Scale: 1 * Manual P.T.

FOB: PICK-UP

This Load: 28.08 TONS

Load No: 42

Shipped: 1,248.98 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727158**
8/28/2025 11:56:08AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	95,720	43.42	47.86
Tare	37,580	17.05	18.79
Net	58,140	26.37	29.07
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.07 TONS

Load No: 43
Shipped: 1,278.05 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727160**
8/28/2025 12:00:21PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB157SD SCARCELLA BROS 157SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	101,160	45.89	50.58
Tare	40,420	18.33	20.21
Net	60,740	27.55	30.37
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.37 TONS

Load No: 44
Shipped: 1,308.42 TONS

Comments:

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727161**
8/28/2025 12:02:33PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,300	44.13	48.65
Tare	37,500	17.01	18.75
Net	59,800	27.12	29.90
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.90 TONS

Load No: 45

Shipped: 1,338.32 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727164**
8/28/2025 12:08:12PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARSELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,280	45.03	49.64
Tare	38,260	17.35	19.13
Net	61,020	27.68	30.51

Scale: 1 * Manual P. T.

FOB: PICK-UP

This Load: 30.51 TONS

Load No: 46

Shipped: 1,368.83 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727165**
8/28/2025 12:11:13PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,260	44.57	49.13
Tare	37,320	16.93	18.66
Net	60,940	27.64	30.47
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.47 TONS

Load No: 47

Shipped: 1,399.30 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727172**
8/28/2025 12:45:22PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB113TT SCARCELLA BROS 113TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	103,640	47.01	51.82
Tare	43,020	19.51	21.51
Net	60,620	27.50	30.31
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.31 TONS

Load No: 48

Shipped: 1,429.61 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727174**
8/28/2025 12:53:38PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB185SD SCARCELLA BROS 185SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	102,900	46.67	51.45
Tare	40,100	18.19	20.05
Net	62,800	28.49	31.40
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 31.40 TONS

Load No: 49

Shipped: 1,461.01 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727175**
8/28/2025 12:54:50PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB176BD SCB176BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,420	44.64	49.21
Tare	39,520	17.93	19.76
Net	58,900	26.72	29.45

Scale: 1 * Manual P. T.

FOB: PICK-UP

This Load: 29.45 TONS

Load No: 50

Shipped: 1,490.46 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727177

8/28/2025

1:02:11PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB112TT SCARCELLA BROS 112TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	104,100	47.22	52.05
Tare	44,820	20.33	22.41
Net	59,280	26.89	29.64
Scale: 1 * Manual P.T.			

FOB: PICK-UP

This Load: 29.64 TONS

Load No: 51

Shipped: 1,520.10 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727179

8/28/2025

1:07:54PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB181SD SCARCELLA BROS 181SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	102,320	46.41	51.16
Tare	40,480	18.36	20.24
Net	61,840	28.05	30.92
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.92 TONS

Load No: 52

Shipped: 1,551.02 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727180

8/28/2025

1:08:44PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	103,600	46.99	51.80
Tare	40,100	18.19	20.05
Net	63,500	28.80	31.75
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 31.75 TONS

Load No: 53

Shipped: 1,582.77 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727181

8/28/2025

1:12:12PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARCELLA BROS 186SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	101,280	45.94	50.64
Tare	39,920	18.11	19.96
Net	61,360	27.83	30.68
Scale: 1			

FOB: PICK-UP

This Load: 30.68 TONS

Load No: 54

Shipped: 1,613.45 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.
8/28/2025

58727182
1:13:08PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB180SD SCARCELLA BROS 180SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,040	44.47	49.02
Tare	40,440	18.34	20.22
Net	57,600	26.13	28.80
Scale: 1 * Manual P.T.			

FOB: PICK-UP

This Load: 28.80 TONS

Load No: 55

Shipped: 1,642.25 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED
BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT
INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE
RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727186

8/28/2025

1:36:57PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,780	44.81	49.39
Tare	37,580	17.05	18.79
Net	61,200	27.76	30.60
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.60 TONS

Load No: 56

Shipped: 1,672.85 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727187**
8/28/2025 1:39:23PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,040	44.02	48.52
Tare	37,500	17.01	18.75
Net	59,540	27.01	29.77
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.77 TONS

Load No: 57

Shipped: 1,702.62 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.
8/28/2025

58727188
1:40:52PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Vehicle: SCB157SD SCARSELLA BROS 157SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,480	45.12	49.74
Tare	40,420	18.33	20.21
Net	59,060	26.79	29.53
Scale: 1 * Manual P. T.			

Comments:

FOB: PICK-UP

This Load: 29.53 TONS

Load No: 58

Shipped: 1,732.15 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727189

8/28/2025

1:44:30PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,240	44.11	48.62
Tare	38,260	17.35	19.13
Net	58,980	26.75	29.49
Scale:	1	* Manual P. T	

FOB: PICK-UP

This Load: 29.49 TONS

Load No: 59

Shipped: 1,761.64 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COMMSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727196**
8/28/2025 2:25:06PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB176BD SCB176BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	102,300	46.40	51.15
Tare	39,520	17.93	19.76
Net	62,780	28.48	31.39
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 31.39 TONS

Load No: 60

Shipped: 1,793.03 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. **58727197**
8/28/2025 2:26:27PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB185SD SCARCELLA BROS 185SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,360	45.52	50.18
Tare	40,100	18.19	20.05
Net	60,260	27.33	30.13
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.13 TONS

Load No: 61

Shipped: 1,823.16 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727207

8/29/2025

7:13:13AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	95,260	43.21	47.63
Tare	37,260	16.90	18.63
Net	58,000	26.31	29.00
Scale:	1		

FOB: PICK-UP

This Load: 29.00 TONS

Load No: 1

Shipped: 29.00 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727209

8/29/2025

7:19:20AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,900	45.31	49.95
Tare	37,480	17.00	18.74
Net	62,420	28.31	31.21
Scale:	1		

FOB: PICK-UP

This Load: 31.21 TONS

Load No: 2

Shipped: 60.21 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727210

8/29/2025

7:21:46AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,520	44.69	49.26
Tare	38,220	17.34	19.11
Net	60,300	27.35	30.15
Scale:	1		

FOB: PICK-UP

This Load: 30.15 TONS

Load No: 3

Shipped: 90.36 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727211

8/29/2025

7:25:45AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	95,800	43.45	47.90
Tare	37,320	16.93	18.66
Net	58,480	26.53	29.24
Scale:	1		

FOB: PICK-UP

This Load: 29.24 TONS

Load No: 4

Shipped: 119.60 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727212

8/29/2025

8:28:21AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,460	44.66	49.23
Tare	37,260	16.90	18.63
Net	61,200	27.76	30.60
Scale: 1 * P T			

FOB: PICK-UP

This Load: 30.60 TONS

Load No: 5

Shipped: 150.20 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED EXPOSURE TO CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT DISABILITY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE PROTECTIVE EQUIPMENT AND RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727213

8/29/2025

8:46:38AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,820	44.37	48.91
Tare	38,220	17.34	19.11
Net	59,600	27.03	29.80
Scale: 1 * P T			

FOB: PICK-UP

This Load: 29.80 TONS

Load No: 6

Shipped: 180.00 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727214

8/29/2025

8:51:51AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,360	44.62	49.18
Tare	37,480	17.00	18.74
Net	60,880	27.61	30.44
Scale:	1	* P T	

FOB: PICK-UP

This Load: 30.44 TONS

Load No: 7
Shipped: 210.44 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727216

8/29/2025

8:56:29AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,080	44.94	49.54
Tare	37,320	16.93	18.66
Net	61,760	28.01	30.88
Scale:	1	* P T	

FOB: PICK-UP

This Load: 30.88 TONS

Load No: 8

Shipped: 241.32 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727224

8/29/2025

9:51:53AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,140	44.52	49.07
Tare	37,260	16.90	18.63
Net	60,880	27.61	30.44
Scale:	1	* P T	

FOB: PICK-UP

This Load: 30.44 TONS

Load No: 9

Shipped: 271.76 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727226

8/29/2025

10:09:17AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,080	44.94	49.54
Tare	38,220	17.34	19.11
Net	60,860	27.61	30.43
Scale: 1 * P T			

FOB: PICK-UP

This Load: 30.43 TONS

Load No: 10

Shipped: 302.19 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727229

8/29/2025

10:24:42AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,100	44.04	48.55
Tare	37,320	16.93	18.66
Net	59,780	27.12	29.89
Scale:	1	* P. I.	

FOB: PICK-UP

This Load: 29.89 TONS

Load No: 11

Shipped: 332.08 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727230

8/29/2025

10:28:42AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,720	44.78	49.36
Tare	37,480	17.00	18.74
Net	61,240	27.78	30.62
Scale:	1	* P T	

FOB: PICK-UP

This Load: 30.62 TONS

Load No: 12

Shipped: 362.70 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727237

8/29/2025

11:18:05AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	96,940	43.97	48.47
Tare	37,320	16.93	18.66
Net	59,620	27.04	29.81
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 29.81 TONS

Load No: 13

Shipped: 392.51 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727238

8/29/2025

11:35:50AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,860	44.39	48.93
Tare	38,220	17.34	19.11
Net	59,640	27.05	29.82
Scale:	1	* P T	

FOB: PICK-UP

This Load: 29.82 TONS

Load No: 14

Shipped: 422.33 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727240

8/29/2025

11:49:50AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,260	45.02	49.63
Tare	37,320	16.93	18.66
Net	61,940	28.10	30.97
Scale:	1	* P T	

FOB: PICK-UP

This Load: 30.97 TONS

Load No: 15

Shipped: 453.30 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727243

8/29/2025

12:03:18PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,560	44.25	48.78
Tare	37,480	17.00	18.74
Net	60,080	27.25	30.04
Scale:	1	* P T	

FOB: PICK-UP

This Load: 30.04 TONS

Load No: 16

Shipped: 483.34 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727417

9/3/2025

2:27:51PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	102,880	46.67	51.44
Tare	43,240	19.61	21.62
Net	59,640	27.05	29.82
Scale:	1	* P.T.	

FOB: PICK-UP

This Load: 29.82 TONS

Load No: 37

Shipped: 1,123.40 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727415

9/3/2025

2:06:40PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	101,160	45.89	50.58
Tare	38,240	17.35	19.12
Net	62,920	28.54	31.46
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 31.46 TONS

Load No: 36

Shipped: 1,093.58 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727414

9/3/2025

2:04:55PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,360	44.62	49.18
Tare	37,320	16.93	18.66
Net	61,040	27.69	30.52
Scale: 1 * P T			

FOB: PICK-UP

This Load: 30.52 TONS

Load No: 35

Shipped: 1,062.12 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727412

9/3/2025

1:54:29PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB113TT SCARCELLA BROS 113TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	104,560	47.43	52.28
Tare	43,060	19.53	21.53
Net	61,500	27.90	30.75
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.75 TONS

Load No: 34

Shipped: 1,031.60 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727407

9/3/2025

1:31:07PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,820	44.82	49.41
Tare	37,140	16.85	18.57
Net	61,680	27.98	30.84
Scale:	1		

FOB: PICK-UP

This Load: 30.84 TONS

Load No: 33

Shipped: 1,000.85 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727405

9/3/2025

1:25:36PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,760	44.80	49.38
Tare	37,360	16.95	18.68
Net	61,400	27.85	30.70
Scale: 1 * Manual P.T.			

FOB: PICK-UP

This Load: 30.70 TONS

Load No: 32

Shipped: 970.01 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727401

9/3/2025

1:13:28PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB178TT SCARSELLA BROS 178TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	101,840	46.19	50.92
Tare	41,360	18.76	20.68
Net	60,480	27.43	30.24
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.24 TONS

Load No: 31

Shipped: 939.31 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727400

9/3/2025

12:58:58PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	103,120	46.77	51.56
Tare	43,240	19.61	21.62
Net	59,880	27.16	29.94
Scale:	1		

FOB: PICK-UP

This Load: 29.94 TONS

Load No: 30

Shipped: 909.07 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727397

9/3/2025

12:37:05PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,200	45.00	49.60
Tare	38,240	17.35	19.12
Net	60,960	27.65	30.48
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.48 TONS

Load No: 29

Shipped: 879.13 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727394

9/3/2025

12:24:48PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,500	44.68	49.25
Tare	37,380	16.96	18.69
Net	61,120	27.72	30.56
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load:	30.56 TONS
Load No:	28
Shipped:	848.65 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727393

9/3/2025

12:23:27PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,580	44.72	49.29
Tare	37,320	16.93	18.66
Net	61,260	27.79	30.63
Scale: 1 * P.T.			

FOB: PICK-UP

This Load:	30.63 TONS
Load No:	27
Shipped:	818.09 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727390

9/3/2025

12:10:26PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB113TT SCARCELLA BROS 113TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	101,600	46.08	50.80
Tare	43,060	19.53	21.53
Net	58,540	26.55	29.27
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.27 TONS

Load No: 26

Shipped: 787.46 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727386

9/3/2025

11:55:28AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,280	44.58	49.14
Tare	37,420	16.97	18.71
Net	60,860	27.61	30.43
Scale:	1	* Manual P. T	

FOB: PICK-UP

This Load:	30.43 TONS
Load No:	25
Shipped:	758.19 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727385

9/3/2025

11:51:13AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,700	44.32	48.85
Tare	37,360	16.95	18.68
Net	60,340	27.37	30.17

Scale: 1 * Manual P. T.

FOB: PICK-UP

This Load: 30.17 TONS

Load No: 24

Shipped: 727.76 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727383

9/3/2025

11:35:26AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB178TT SCARSELLA BROS 178TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	101,980	46.26	50.99
Tare	41,360	18.76	20.68
Net	60,620	27.50	30.31
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 30.31 TONS

Load No: 23
Shipped: 697.59 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727381

9/3/2025

11:24:01AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	102,480	46.48	51.24
Tare	43,340	19.66	21.67
Net	59,140	26.83	29.57
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.57 TONS

Load No: 22

Shipped: 667.28 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727378

9/3/2025

11:07:13AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: []

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,140	44.52	49.07
Tare	38,240	17.35	19.12
Net	59,900	27.17	29.95
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 29.95 TONS

Load No: 21

Shipped: 637.71 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727374

9/3/2025

10:55:56AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: []

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,280	44.13	48.64
Tare	37,380	16.96	18.69
Net	59,900	27.17	29.95
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 29.95 TONS

Load No: 20

Shipped: 607.76 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727373

9/3/2025

10:53:51AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,520	45.14	49.76
Tare	37,320	16.93	18.66
Net	62,200	28.21	31.10

Scale: 1 * P T

FOB: PICK-UP

This Load:	31.10 TONS
Load No:	19
Shipped:	577.81 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727370

9/3/2025

10:40:02AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB113TT SCARCELLA BROS 113TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	101,240	45.92	50.62
Tare	43,060	19.53	21.53
Net	58,180	26.39	29.09
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load:	29.09 TONS
Load No:	18
Shipped:	546.71 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727368

9/3/2025

10:29:12AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	96,760	43.89	48.38
Tare	37,420	16.97	18.71
Net	59,340	26.92	29.67

Scale: 1 * Manual P.T.

FOB: PICK-UP

This Load:	29.67 TONS
Load No:	17
Shipped:	517.62 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727365

9/3/2025

10:18:09AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: []

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	96,700	43.86	48.35
Tare	37,360	16.95	18.68
Net	59,340	26.92	29.67
Scale:	1	* Manual P T	

FOB: PICK-UP

This Load:	29.67 TONS
Load No:	16
Shipped:	487.95 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727362

9/3/2025

9:54:12AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	105,500	47.85	52.75
Tare	43,340	19.66	21.67
Net	62,160	28.20	31.08
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 31.08 TONS

Load No: 15

Shipped: 458.28 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727357

9/3/2025

9:28:38AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARSELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,660	45.66	50.33
Tare	38,240	17.35	19.12
Net	62,420	28.31	31.21
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load:	31.21 TONS
Load No:	14
Shipped:	427.20 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.

gci re



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727356

9/3/2025

9:24:34AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	96,360	43.71	48.18
Tare	37,380	16.96	18.69
Net	58,980	26.75	29.49
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load:	29.49 TONS
Load No:	13
Shipped:	395.99 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727355

9/3/2025

9:23:11AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: []

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,520	45.14	49.76
Tare	37,320	16.93	18.66
Net	62,200	28.21	31.10
Scale:	1	* P T	

FOB: PICK-UP

This Load:	31.10 TONS
Load No:	12
Shipped:	366.50 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727350

9/3/2025

9:03:11AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB113TT SCARCELLA BROS 113TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	102,420	46.46	51.21
Tare	43,060	19.53	21.53
Net	59,360	26.93	29.68
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.68 TONS

Load No: 11
Shipped: 335.40 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727347

9/3/2025

8:53:18AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,840	44.38	48.92
Tare	37,420	16.97	18.71
Net	60,420	27.41	30.21
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load:	30.21 TONS
Load No:	10
Shipped:	305.72 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727346

9/3/2025

8:50:25AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,080	44.49	49.04
Tare	37,360	16.95	18.68
Net	60,720	27.54	30.36
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.36 TONS

Load No: 9

Shipped: 275.51 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727342

9/3/2025

8:30:41AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	104,440	47.37	52.22
Tare	43,340	19.66	21.67
Net	61,100	27.71	30.55
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 30.55 TONS

Load No: 8
Shipped: 245.15 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727338

9/3/2025

7:34:57AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,860	44.39	48.93
Tare	37,380	16.96	18.69
Net	60,480	27.43	30.24
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 30.24 TONS

Load No: 7
Shipped: 214.60 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727337

9/3/2025

7:32:45AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARSELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,360	45.52	50.18
Tare	38,240	17.35	19.12
Net	62,120	28.18	31.06
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 31.06 TONS

Load No: 6

Shipped: 184.36 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727336

9/3/2025

7:29:17AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,500	45.13	49.75
Tare	37,320	16.93	18.66
Net	62,180	28.20	31.09
Scale:	1		

FOB: PICK-UP

This Load:	31.09 TONS
Load No:	5
Shipped:	153.30 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727332

9/3/2025

7:11:26AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB113TT SCARCELLA BROS 113TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	105,480	47.84	52.74
Tare	43,060	19.53	21.53
Net	62,420	28.31	31.21
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load:	31.21 TONS
Load No:	4
Shipped:	122.21 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727331

9/3/2025

7:08:33AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,240	44.56	49.12
Tare	37,360	16.95	18.68
Net	60,880	27.61	30.44
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.44 TONS

Load No: 3

Shipped: 91.00 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727330

9/3/2025

7:05:01AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,240	44.11	48.62
Tare	37,420	16.97	18.71
Net	59,820	27.13	29.91
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 29.91 TONS

Load No: 2
Shipped: 60.56 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727329

9/3/2025

7:02:39AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	104,640	47.46	52.32
Tare	43,340	19.66	21.67
Net	61,300	27.81	30.65
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.65 TONS

Load No: 1
Shipped: 30.65 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727574

9/5/2025

1:49:33PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,740	45.69	50.37
Tare	38,220	17.34	19.11
Net	62,520	28.36	31.26
Scale: 1 * P T			

FOB: PICK-UP

This Load: 31.26 TONS

Load No: 15

Shipped: 469.25 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727572

9/5/2025

1:44:55PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code
Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,000	45.36	50.00
Tare	37,340	16.94	18.67
Net	62,660	28.42	31.33
Scale:	1	* P T	

FOB: PICK-UP

This Load: 31.33 TONS

Load No: 14
Shipped: 437.99 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727571

9/5/2025

1:43:17PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,140	45.42	50.07
Tare	37,280	16.91	18.64
Net	62,860	28.51	31.43
Scale:	1	* P T	

FOB: PICK-UP

This Load: 31.43 TONS

Load No: 13

Shipped: 406.66 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.

gci rev. 04/21



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727558

9/5/2025

11:58:51AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	101,480	46.03	50.74
Tare	37,340	16.94	18.67
Net	64,140	29.09	32.07
Scale:	1	* P T	

FOB: PICK-UP

This Load: 32.07 TONS

Load No: 12

Shipped: 375.23 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727557

9/5/2025

11:55:08AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	103,180	46.80	51.59
Tare	38,220	17.34	19.11
Net	64,960	29.47	32.48
Scale:	1	* P.T.	

FOB: PICK-UP

This Load: 32.48 TONS

Load No: 11

Shipped: 343.16 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727556

9/5/2025

11:53:50AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	101,580	46.08	50.79
Tare	37,280	16.91	18.64
Net	64,300	29.17	32.15
Scale:	1	* P T	

FOB: PICK-UP

This Load:	32.15 TONS
Load No:	10
Shipped:	310.68 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No:

58727544

9/5/2025

10:34:42AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,000	44.91	49.50
Tare	37,340	16.94	18.67
Net	61,660	27.97	30.83
Scale:	1	* P T	

FOB: PICK-UP

This Load: 30.83 TONS

Load No: 9

Shipped: 278.53 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727542

9/5/2025

10:23:56AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	101,840	46.19	50.92
Tare	38,220	17.34	19.11
Net	63,620	28.86	31.81
Scale:	1	* P T	

FOB: PICK-UP

This Load: 31.81 TONS

Load No: 8

Shipped: 247.70 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727531

9/5/2025

9:06:41AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,680	44.76	49.34
Tare	37,340	16.94	18.67
Net	61,340	27.82	30.67
Scale: 1 * P T			

FOB: PICK-UP

This Load: 30.67 TONS

Load No: 7
Shipped: 215.89 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727528

9/5/2025

8:52:00AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,780	45.71	50.39
Tare	38,220	17.34	19.11
Net	62,560	28.38	31.28
Scale: 1 * P T			

FOB: PICK-UP

This Load:	31.28 TONS
Load No:	6
Shipped:	185.22 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727524

9/5/2025

7:28:02AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	96,560	43.80	48.28
Tare	37,340	16.94	18.67
Net	59,220	26.86	29.61
Scale:	1		

FOB: PICK-UP

This Load: 29.61 TONS

Load No: 5
Shipped: 153.94 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727522

9/5/2025

7:21:57AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,140	45.42	50.07
Tare	38,220	17.34	19.11
Net	61,920	28.09	30.96
Scale:	1		

FOB: PICK-UP

This Load: 30.96 TONS

Load No: 4
Shipped: 124.33 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727521

9/5/2025

7:20:26AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,660	45.66	50.33
Tare	37,280	16.91	18.64
Net	63,380	28.75	31.69
Scale:	1		

FOB: PICK-UP

This Load: 31.69 TONS

Load No: 3
Shipped: 93.37 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727519

9/5/2025

7:17:31AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,200	44.54	49.10
Tare	37,280	16.91	18.64
Net	60,920	27.63	30.46
Scale:	1		

FOB: PICK-UP

This Load:	30.46 TONS
Load No:	2
Shipped:	61.68 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727518

9/5/2025

7:12:47AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,840	45.29	49.92
Tare	37,400	16.96	18.70
Net	62,440	28.32	31.22
Scale:	1		

FOB: PICK-UP

This Load: 31.22 TONS

Load No: 1
Shipped: 31.22 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

ORIGINAL

Ticket No.

58727677

9/9/2025

8:57:25AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	105,500	47.85	52.75
Tare	43,200	19.60	21.60
Net	62,300	28.26	31.15
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 31.15 TONS

Load No: 2

Shipped: 61.55 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT DISABILITY. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION. IF YOU ARE NOT SURE OF THE APPROPRIATE

ORIGINAL

Ticket No.

58727673

9/9/2025

7:05:38AM



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	104,000	47.17	52.00
Tare	43,200	19.60	21.60
Net	60,800	27.58	30.40
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.40 TONS

Load No: 1
Shipped: 30.40 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED EXPOSURE TO CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT DISABILITY OR DEATH. FOR A COMPLETE LIST OF HEALTH EFFECTS, SEE THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION, INCLUDING INFORMATION ON APPROPRIATE PROTECTIVE EQUIPMENT.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727323

9/2/2025

2:53:10PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,680	45.21	49.84
Tare	40,160	18.22	20.08
Net	59,520	27.00	29.76
Scale:	1	* P T	

FOB: PICK-UP

This Load: 29.76 TONS

Load No: 21

Shipped: 638.67 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727321

9/2/2025

2:14:01PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,760	45.70	50.38
Tare	37,100	16.83	18.55
Net	63,660	28.88	31.83
Scale: 1 * P T			

FOB: PICK-UP

This Load:	31.83 TONS
Load No:	20
Shipped:	608.91 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727314

9/2/2025

1:25:17PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	100,940	45.79	50.47
Tare	40,160	18.22	20.08
Net	60,780	27.57	30.39
Scale:	1	* P.T.	

FOB: PICK-UP

This Load: 30.39 TONS

Load No: 19

Shipped: 577.08 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727313

9/2/2025

1:22:04PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,080	44.03	48.54
Tare	37,340	16.94	18.67
Net	59,740	27.10	29.87
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.87 TONS

Load No: 18

Shipped: 546.69 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727311

9/2/2025

1:05:04PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,080	44.49	49.04
Tare	37,300	16.92	18.65
Net	60,780	27.57	30.39
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.39 TONS

Load No: 17

Shipped: 516.82 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727309

9/2/2025

12:52:39PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,260	45.48	50.13
Tare	37,100	16.83	18.55
Net	63,160	28.65	31.58
Scale:	1		

FOB: PICK-UP

This Load: 31.58 TONS

Load No: 16

Shipped: 486.43 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727303

9/2/2025

12:08:17PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,280	44.13	48.64
Tare	37,340	16.94	18.67
Net	59,940	27.19	29.97
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load:	29.97 TONS
Load No:	15
Shipped:	454.85 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727302

9/2/2025

11:58:50AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,340	44.61	49.17
Tare	40,160	18.22	20.08
Net	58,180	26.39	29.09
Scale:	1	* P T	

FOB: PICK-UP

This Load: 29.09 TONS

Load No: 14

Shipped: 424.88 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727297

9/2/2025

11:18:38AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,580	45.17	49.79
Tare	37,340	16.94	18.67
Net	62,240	28.23	31.12
Scale:	1	* Manual P. T	

FOB: PICK-UP

This Load: 31.12 TONS

Load No: 13
Shipped: 395.79 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727296

9/2/2025

11:13:33AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: []

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,060	44.48	49.03
Tare	37,300	16.92	18.65
Net	60,760	27.56	30.38

Scale: 1 * Manual P.T.

FOB: PICK-UP

This Load:	30.38 TONS
Load No:	12
Shipped:	364.67 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727294

9/2/2025

10:53:42AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,320	45.05	49.66
Tare	37,340	16.94	18.67
Net	61,980	28.11	30.99
Scale:	1	* Manual P T	

FOB: PICK-UP

This Load: 30.99 TONS

Load No: 11
Shipped: 334.29 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727288

9/2/2025

10:27:26AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,880	45.30	49.94
Tare	40,160	18.22	20.08
Net	59,720	27.09	29.86
Scale:	1		

FOB: PICK-UP

This Load: 29.86 TONS

Load No: 10

Shipped: 303.30 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727284

9/2/2025

9:54:16AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: []

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,380	44.62	49.19
Tare	37,340	16.94	18.67
Net	61,040	27.69	30.52
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load:	30.52 TONS
Load No:	9
Shipped:	273.44 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727282

9/2/2025

9:47:16AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,220	45.01	49.61
Tare	37,300	16.92	18.65
Net	61,920	28.09	30.96

Scale: 1 * Manual P T

FOB: PICK-UP

This Load:	30.96 TONS
Load No:	8
Shipped:	242.92 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727281

9/2/2025

9:36:26AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,020	44.91	49.51
Tare	37,340	16.94	18.67
Net	61,680	27.98	30.84
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 30.84 TONS

Load No: 7
Shipped: 211.96 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727274

9/2/2025

8:33:41AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,780	44.35	48.89
Tare	37,340	16.94	18.67
Net	60,440	27.42	30.22
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 30.22 TONS

Load No: 6

Shipped: 181.12 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727273

9/2/2025

8:23:35AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	95,380	43.26	47.69
Tare	37,300	16.92	18.65
Net	58,080	26.34	29.04
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.04 TONS

Load No: 5
Shipped: 150.90 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727272

9/2/2025

8:16:02AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,300	44.13	48.65
Tare	37,340	16.94	18.67
Net	59,960	27.20	29.98
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 29.98 TONS

Load No: 4

Shipped: 121.86 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727267

9/2/2025

7:09:10AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,620	45.64	50.31
Tare	37,340	16.94	18.67
Net	63,280	28.70	31.64
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 31.64 TONS

Load No: 3
Shipped: 91.88 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727266

9/2/2025

7:02:13AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,460	44.21	48.73
Tare	37,300	16.92	18.65
Net	60,160	27.29	30.08
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 30.08 TONS

Load No: 2
Shipped: 60.24 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727265

9/2/2025

6:56:20AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,660	44.30	48.83
Tare	37,340	16.94	18.67
Net	60,320	27.36	30.16
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 30.16 TONS

Load No: 1
Shipped: 30.16 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727502

9/4/2025

1:47:55PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,780	44.35	48.89
Tare	37,300	16.92	18.65
Net	60,480	27.43	30.24
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.24 TONS

Load No: 32

Shipped: 974.41 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727501

9/4/2025

1:43:36PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,560	45.16	49.78
Tare	38,220	17.34	19.11
Net	61,340	27.82	30.67
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.67 TONS

Load No: 31

Shipped: 944.17 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.

gci rev. 04/21



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727499

9/4/2025

1:36:56PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,520	45.60	50.26
Tare	37,340	16.94	18.67
Net	63,180	28.66	31.59
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 31.59 TONS

Load No: 30

Shipped: 913.50 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727498

9/4/2025

1:30:49PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

Vehicle: SCB178TT SCARSELLA BROS 178TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	104,160	47.25	52.08
Tare	41,380	18.77	20.69
Net	62,780	28.48	31.39
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 31.39 TONS

Load No: 29

Shipped: 881.91 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727497

9/4/2025

1:26:36PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,400	44.63	49.20
Tare	37,180	16.86	18.59
Net	61,220	27.77	30.61
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.61 TONS

Load No: 28

Shipped: 850.52 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727493

9/4/2025

12:57:47PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	96,380	43.72	48.19
Tare	37,160	16.86	18.58
Net	59,220	26.86	29.61
Scale:	1		

FOB: PICK-UP

This Load: 29.61 TONS

Load No: 27
Shipped: 819.91 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727487

9/4/2025

12:08:37PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code
Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	96,920	43.96	48.46
Tare	37,300	16.92	18.65
Net	59,620	27.04	29.81
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 29.81 TONS

Load No: 26

Shipped: 790.30 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727486

9/4/2025

12:05:22PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,540	45.15	49.77
Tare	38,220	17.34	19.11
Net	61,320	27.81	30.66
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.66 TONS

Load No: 25
Shipped: 760.49 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727485

9/4/2025

12:03:40PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,460	44.66	49.23
Tare	37,340	16.94	18.67
Net	61,120	27.72	30.56
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.56 TONS

Load No: 24

Shipped: 729.83 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727484

9/4/2025

12:02:05PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB178TT SCARSELLA BROS 178TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	103,160	46.79	51.58
Tare	41,380	18.77	20.69
Net	61,780	28.02	30.89
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.89 TONS

Load No: 23

Shipped: 699.27 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727482

9/4/2025

11:55:04AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,680	44.76	49.34
Tare	37,180	16.86	18.59
Net	61,500	27.90	30.75
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.75 TONS

Load No: 22

Shipped: 668.38 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727473

9/4/2025

11:22:08AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,620	44.73	49.31
Tare	37,380	16.96	18.69
Net	61,240	27.78	30.62
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.62 TONS

Load No: 21

Shipped: 637.63 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727468

9/4/2025

10:37:35AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,300	44.59	49.15
Tare	37,300	16.92	18.65
Net	61,000	27.67	30.50
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.50 TONS

Load No: 20

Shipped: 607.01 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727467

9/4/2025

10:36:02AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,060	45.39	50.03
Tare	38,220	17.34	19.11
Net	61,840	28.05	30.92
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 30.92 TONS

Load No: 19

Shipped: 576.51 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727465

9/4/2025

10:29:55AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	96,020	43.55	48.01
Tare	37,340	16.94	18.67
Net	58,680	26.62	29.34
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.34 TONS

Load No: 18

Shipped: 545.59 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727464

9/4/2025

10:27:36AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB178TT SCARSELLA BROS 178TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	101,360	45.98	50.68
Tare	41,380	18.77	20.69
Net	59,980	27.21	29.99
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 29.99 TONS

Load No: 17

Shipped: 516.25 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727463

9/4/2025

10:26:05AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,820	45.28	49.91
Tare	37,180	16.86	18.59
Net	62,640	28.41	31.32
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 31.32 TONS

Load No: 16

Shipped: 486.26 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727459

9/4/2025

9:55:50AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,120	44.51	49.06
Tare	37,380	16.96	18.69
Net	60,740	27.55	30.37
Scale: 1 * Manual P T			

FOB: PICK-UP

This Load: 30.37 TONS

Load No: 15

Shipped: 454.94 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727450

9/4/2025

9:08:13AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	96,440	43.74	48.22
Tare	38,220	17.34	19.11
Net	58,220	26.41	29.11
Scale: 1 * Manual P.T.			

FOB: PICK-UP

This Load: 29.11 TONS

Load No: 14

Shipped: 424.57 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727449

9/4/2025

9:06:01AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,460	45.11	49.73
Tare	37,300	16.92	18.65
Net	62,160	28.20	31.08
Scale: 1 * Manual P.T.			

FOB: PICK-UP

This Load: 31.08 TONS

Load No: 13

Shipped: 395.46 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727447

9/4/2025

8:59:09AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,140	44.52	49.07
Tare	37,340	16.94	18.67
Net	60,800	27.58	30.40
Scale: 1 * Manual P.T.			

FOB: PICK-UP

This Load: 30.40 TONS

Load No: 12
Shipped: 364.38 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727445

9/4/2025

8:52:23AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB178TT SCARSELLA BROS 178TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,980	45.80	50.49
Tare	41,380	18.77	20.69
Net	59,600	27.03	29.80
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.80 TONS

Load No: 11

Shipped: 333.98 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727444

9/4/2025

8:49:59AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,820	44.37	48.91
Tare	37,180	16.86	18.59
Net	60,640	27.51	30.32
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.32 TONS

Load No: 10

Shipped: 304.18 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727443

9/4/2025

8:47:27AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB113TT SCARCELLA BROS 113TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	103,400	46.90	51.70
Tare	43,040	19.52	21.52
Net	60,360	27.38	30.18
Scale: 1 * Manual P T			

FOB: PICK-UP

This Load: 30.18 TONS

Load No: 9
Shipped: 273.86 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727441

9/4/2025

8:27:04AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,580	44.72	49.29
Tare	37,380	16.96	18.69
Net	61,200	27.76	30.60
Scale: 1 * Manual P.T.			

FOB: PICK-UP

This Load: 30.60 TONS

Load No: 8

Shipped: 243.68 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727436

9/4/2025

7:21:36AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,460	44.66	49.23
Tare	38,220	17.34	19.11
Net	60,240	27.32	30.12
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 30.12 TONS

Load No: 7

Shipped: 213.08 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727435

9/4/2025

7:19:46AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,840	44.83	49.42
Tare	37,300	16.92	18.65
Net	61,540	27.91	30.77
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 30.77 TONS

Load No: 6
Shipped: 182.96 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727434

9/4/2025

7:14:41AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,820	44.82	49.41
Tare	37,340	16.94	18.67
Net	61,480	27.89	30.74
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.74 TONS

Load No: 5

Shipped: 152.19 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727432

9/4/2025

7:11:08AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,200	44.54	49.10
Tare	37,180	16.86	18.59
Net	61,020	27.68	30.51
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 30.51 TONS

Load No: 4

Shipped: 121.45 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No. 58727431

9/4/2025

7:08:00AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB178TT SCARSELLA BROS 178TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	100,960	45.79	50.48
Tare	41,380	18.77	20.69
Net	59,580	27.03	29.79
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 29.79 TONS

Load No: 3

Shipped: 90.94 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727430

9/4/2025

7:06:38AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB113TT SCARCELLA BROS 113TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	103,700	47.04	51.85
Tare	43,040	19.52	21.52
Net	60,660	27.51	30.33
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.33 TONS

Load No: 2

Shipped: 61.15 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727429

9/4/2025

7:05:23AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,020	44.91	49.51
Tare	37,380	16.96	18.69
Net	61,640	27.96	30.82
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 30.82 TONS

Load No: 1

Shipped: 30.82 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.

COPY

Ticket No. .

58726987

8/27/2025

6:54:05AM



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,920	44.87	49.46
Tare	40,100	18.19	20.05
Net	58,820	26.68	29.41
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 29.41 TONS

Load No: 1
Shipped: 29.41 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.

gci rev. 04/21

COPY

Ticket No.

58726988

8/27/2025

6:57:50AM



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB185SD SCARCELLA BROS 185SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,640	45.20	49.82
Tare	40,000	18.14	20.00
Net	59,640	27.05	29.82
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 29.82 TONS

Load No: 2
Shipped: 59.23 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.

gci rev. 04/21



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58726990

8/27/2025

7:06:11AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARSELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,720	44.33	48.86
Tare	38,220	17.34	19.11
Net	59,500	26.99	29.75
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 29.75 TONS

Load No: 3

Shipped: 88.98 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58726991

8/27/2025

7:11:21AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB181SD SCARCELLA BROS 181SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,320	45.50	50.16
Tare	40,500	18.37	20.25
Net	59,820	27.13	29.91
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load:	29.91 TONS
Load No:	4
Shipped:	118.89 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58726992

8/27/2025

7:14:30AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB176BD SCB176BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,640	45.65	50.32
Tare	39,560	17.94	19.78
Net	61,080	27.71	30.54
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 30.54 TONS

Load No: 5

Shipped: 149.43 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.

COPY

Ticket No.

58726994

8/27/2025

7:18:22AM



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARCELLA BROS 186SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	100,500	45.59	50.25
Tare	40,260	18.26	20.13
Net	60,240	27.32	30.12
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 30.12 TONS

Load No: 6

Shipped: 179.55 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58726995

8/27/2025

7:19:53AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB157SD SCARCELLA BROS 157SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,540	45.15	49.77
Tare	40,320	18.29	20.16
Net	59,220	26.86	29.61
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 29.61 TONS

Load No: 7
Shipped: 209.16 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

8/27/2025

7:21:36AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: []

Carrier:

Product - 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	100,160	45.43	50.08
Tare	37,440	16.98	18.72
Net	62,720	28.45	31.36
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 31.36 TONS

Load No: 8

Shipped: 240.52 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.

gci rev. 04/21



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58726999

8/27/2025

7:30:58AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,400	45.54	50.20
Tare	37,700	17.10	18.85
Net	62,700	28.44	31.35
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 31.35 TONS

Load No: 9
Shipped: 271.87 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727001

8/27/2025

8:15:00AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,400	44.18	48.70
Tare	40,100	18.19	20.05
Net	57,300	25.99	28.65
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 28.65 TONS

Load No: 10

Shipped: 300.52 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COMMSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727002

8/27/2025

8:17:49AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB185SD SCARCELLA BROS 185SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,440	44.65	49.22
Tare	40,000	18.14	20.00
Net	58,440	26.51	29.22
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.22 TONS

Load No: 11

Shipped: 329.74 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727004

8/27/2025

8:39:21AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB181SD SCARCELLA BROS 181SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,500	45.59	50.25
Tare	40,500	18.37	20.25
Net	60,000	27.22	30.00
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 30.00 TONS

Load No: 12

Shipped: 359.74 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727005

8/27/2025

8:40:48AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	96,580	43.81	48.29
Tare	38,220	17.34	19.11
Net	58,360	26.47	29.18
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.18 TONS

Load No: 13

Shipped: 388.92 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727008

8/27/2025

8:48:44AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB176BD SCB176BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	100,280	45.49	50.14
Tare	39,560	17.94	19.78
Net	60,720	27.54	30.36
Scale: 1 * Manual P. T			

FOB: PICK-UP

This Load: 30.36 TONS

Load No: 14

Shipped: 419.28 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727010

8/27/2025

8:57:01AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB157SD SCARCELLA BROS 157SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,200	45.45	50.10
Tare	40,320	18.29	20.16
Net	59,880	27.16	29.94
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 29.94 TONS

Load No: 15

Shipped: 449.22 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727012

8/27/2025

9:02:55AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARCELLA BROS 186SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	100,820	45.73	50.41
Tare	40,260	18.26	20.13
Net	60,560	27.47	30.28
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.28 TONS

Load No: 16

Shipped: 479.50 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727013

8/27/2025

9:04:35AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,780	44.81	49.39
Tare	37,440	16.98	18.72
Net	61,340	27.82	30.67
Scale: 1 * Manual P.T.			

FOB: PICK-UP

This Load: 30.67 TONS

Load No: 17

Shipped: 510.17 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727016

8/27/2025

9:12:38AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,500	44.68	49.25
Tare	37,700	17.10	18.85
Net	60,800	27.58	30.40
Scale:	1	* Manual P T	

FOB: PICK-UP

This Load: 30.40 TONS

Load No: 18

Shipped: 540.57 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727018

8/27/2025

9:30:04AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,620	44.28	48.81
Tare	40,100	18.19	20.05
Net	57,520	26.09	28.76
Scale:	1	* Manual P T	

FOB: PICK-UP

This Load: 28.76 TONS

Load No: 19

Shipped: 569.33 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727020

8/27/2025

9:38:58AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARCELLA BROS 186SD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,300	45.04	49.65
Tare	40,260	18.26	20.13
Net	59,040	26.78	29.52
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.52 TONS

Load No: 20

Shipped: 598.85 TONS

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727023

8/27/2025

10:07:54AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB166BD SCARSELLA BROS 166BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,820	44.37	48.91
Tare	37,380	16.96	18.69
Net	60,440	27.42	30.22
Scale:	1	* Manual Weight	

FOB: PICK-UP

This Load: 30.22 TONS

Load No: 21

Shipped: 629.07 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727025

8/27/2025

10:13:19AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB181SD SCARCELLA BROS 181SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,540	45.15	49.77
Tare	40,500	18.37	20.25
Net	59,040	26.78	29.52
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.52 TONS

Load No: 22

Shipped: 658.59 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727027

8/27/2025

10:22:55AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	100,860	45.75	50.43
Tare	38,220	17.34	19.11
Net	62,640	28.41	31.32
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 31.32 TONS

Load No: 23

Shipped: 689.91 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727029

8/27/2025

10:25:27AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB157SD SCARCELLA BROS 157SD

License: []

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,820	44.82	49.41
Tare	40,320	18.29	20.16
Net	58,500	26.54	29.25
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.25 TONS

Load No: 24

Shipped: 719.16 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727030

8/27/2025

10:29:16AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARCELLA BROS 186SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	100,960	45.79	50.48
Tare	40,260	18.26	20.13
Net	60,700	27.53	30.35

Scale: 1 * Manual P.T.

FOB: PICK-UP

This Load: 30.35 TONS

Load No: 25

Shipped: 749.51 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727031

8/27/2025

10:31:10AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1874 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,820	44.37	48.91
Tare	37,440	16.98	18.72
Net	60,380	27.39	30.19
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 30.19 TONS

Load No: 26

Shipped: 779.70 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727035

8/27/2025

10:41:11AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB176BD SCB176BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,720	44.33	48.86
Tare	39,560	17.94	19.78
Net	58,160	26.38	29.08
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.08 TONS

Load No: 27

Shipped: 808.78 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727038

8/27/2025

10:50:59AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,440	44.65	49.22
Tare	37,700	17.10	18.85
Net	60,740	27.55	30.37
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.37 TONS

Load No: 28

Shipped: 839.15 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727039

8/27/2025

10:52:07AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: ||

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,420	45.10	49.71
Tare	40,100	18.19	20.05
Net	59,320	26.91	29.66
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.66 TONS

Load No: 29

Shipped: 868.81 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727041

8/27/2025

10:56:24AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB185SD SCARCELLA BROS 185SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,140	44.97	49.57
Tare	40,000	18.14	20.00
Net	59,140	26.83	29.57
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.57 TONS

Load No: 30

Shipped: 898.38 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727047

8/27/2025

11:39:47AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB181SD SCARCELLA BROS 181SD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,820	45.28	49.91
Tare	40,500	18.37	20.25
Net	59,320	26.91	29.66
Scale:	1	* Manual P. T	

FOB: PICK-UP

This Load: 29.66 TONS

Load No: 31

Shipped: 928.04 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727048

8/27/2025

11:54:21AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,040	44.47	49.02
Tare	38,220	17.34	19.11
Net	59,820	27.13	29.91
Scale:	1	* Manual P T	

FOB: PICK-UP

This Load: 29.91 TONS

Load No: 32

Shipped: 957.95 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727049

8/27/2025

11:59:30AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARCELLA BROS 186SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,920	45.78	50.46
Tare	40,260	18.26	20.13
Net	60,660	27.51	30.33
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.33 TONS

Load No: 33
Shipped: 988.28 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727050

8/27/2025

12:01:15PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB157SD SCARCELLA BROS 157SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,460	44.66	49.23
Tare	40,320	18.29	20.16
Net	58,140	26.37	29.07
Scale:	1	* Manual P. T	

FOB: PICK-UP

This Load: 29.07 TONS

Load No: 34

Shipped: 1,017.35 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727051

8/27/2025

12:03:02PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,300	44.59	49.15
Tare	37,440	16.98	18.72
Net	60,860	27.61	30.43
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.43 TONS

Load No: 35

Shipped: 1,047.78 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.

gcl rev. 04/21



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727054

8/27/2025

12:12:04PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB176BD SCB176BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,560	45.61	50.28
Tare	39,560	17.94	19.78
Net	61,000	27.67	30.50
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.50 TONS

Load No: 36

Shipped: 1,078.28 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727055

8/27/2025

12:14:11PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,740	44.33	48.87
Tare	40,100	18.19	20.05
Net	57,640	26.15	28.82
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 28.82 TONS

Load No: 37

Shipped: 1,107.10 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727056

8/27/2025

12:17:10PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB185SD SCARCELLA BROS 185SD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,660	44.30	48.83
Tare	40,000	18.14	20.00
Net	57,660	26.15	28.83
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 28.83 TONS

Load No: 38

Shipped: 1,135.93 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727057

8/27/2025

12:19:30PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,280	45.03	49.64
Tare	37,700	17.10	18.85
Net	61,580	27.93	30.79
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.79 TONS

Load No: 39

Shipped: 1,166.72 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727066

8/27/2025

1:14:55PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB181SD SCARCELLA BROS 181SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	99,340	45.06	49.67
Tare	40,500	18.37	20.25
Net	58,840	26.69	29.42
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 29.42 TONS

Load No: 40

Shipped: 1,196.14 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.

gci rev. 04/21



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727069

8/27/2025

1:32:02PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014
Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARCELLA BROS 186SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,860	44.84	49.43
Tare	40,260	18.26	20.13
Net	58,600	26.58	29.30
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.30 TONS

Load No: 41

Shipped: 1,225.44 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727070

8/27/2025

1:32:53PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB157SD SCARCELLA BROS 157SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,080	44.94	49.54
Tare	40,320	18.29	20.16
Net	58,760	26.65	29.38
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.38 TONS

Load No: 42

Shipped: 1,254.82 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727071

8/27/2025

1:34:54PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

Vehicle: SCB184BD SCARCELLA BROS 184BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	96,940	43.97	48.47
Tare	38,220	17.34	19.11
Net	58,720	26.63	29.36
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.36 TONS

Load No: 43

Shipped: 1,284.18 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727072

8/27/2025

1:36:40PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,600	44.27	48.80
Tare	37,440	16.98	18.72
Net	60,160	27.29	30.08
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.08 TONS

Load No: 44

Shipped: 1,314.26 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.

gci rev. 04/21



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727073

8/27/2025

1:38:56PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB158SD SCARCELLA BROS 158SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,720	44.33	48.86
Tare	40,100	18.19	20.05
Net	57,620	26.14	28.81
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 28.81 TONS

Load No: 45

Shipped: 1,343.07 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727074

8/27/2025

1:42:33PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code
Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB176BD SCB176BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,320	45.50	50.16
Tare	39,560	17.94	19.78
Net	60,760	27.56	30.38
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 30.38 TONS

Load No: 46
Shipped: 1,373.45 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727075

8/27/2025

1:45:03PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB185SD SCARCELLA BROS 185SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,760	44.34	48.88
Tare	40,000	18.14	20.00
Net	57,760	26.20	28.88
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 28.88 TONS

Load No: 47

Shipped: 1,402.33 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727076

8/27/2025

1:51:44PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

Vehicle: SCB175BD SCARCELLA BROS 175BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,740	45.24	49.87
Tare	37,700	17.10	18.85
Net	62,040	28.14	31.02
Scale:	1	* Manual P. T	

FOB: PICK-UP

This Load: 31.02 TONS

Load No: 48

Shipped: 1,433.35 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727662

9/8/2025

2:04:58PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,280	45.03	49.64
Tare	37,680	17.09	18.84
Net	61,600	27.94	30.80
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.80 TONS

Load No: 14

Shipped: 423.53 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd.
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727660

9/8/2025

1:57:28PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	103,820	47.09	51.91
Tare	42,840	19.43	21.42
Net	60,980	27.66	30.49
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 30.49 TONS

Load No: 13

Shipped: 392.73 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727657

9/8/2025

1:35:37PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	98,460	44.66	49.23
Tare	37,340	16.94	18.67
Net	61,120	27.72	30.56
Scale:	1	* P T	

FOB: PICK-UP

This Load: 30.56 TONS

Load No: 12

Shipped: 362.24 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727651

9/8/2025

12:37:07PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	97,560	44.25	48.78
Tare	37,680	17.09	18.84
Net	59,880	27.16	29.94
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 29.94 TONS

Load No: 11

Shipped: 331.68 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727650

9/8/2025

12:28:56PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code
Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	104,080	47.21	52.04
Tare	42,840	19.43	21.42
Net	61,240	27.78	30.62
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.62 TONS

Load No: 10

Shipped: 301.74 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727645

9/8/2025

12:01:47PM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	96,620	43.83	48.31
Tare	37,340	16.94	18.67
Net	59,280	26.89	29.64
Scale:	1	* P.T.	

FOB: PICK-UP

This Load: 29.64 TONS

Load No: 9

Shipped: 271.12 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727636

9/8/2025

10:35:27AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,280	44.58	49.14
Tare	37,340	16.94	18.67
Net	60,940	27.64	30.47
Scale:	1	* P T	

FOB: PICK-UP

This Load: 30.47 TONS

Load No: 8

Shipped: 241.48 TONS

Weighmaster: Granite Construction Company

Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727630

9/8/2025

10:13:28AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,440	44.20	48.72
Tare	37,680	17.09	18.84
Net	59,760	27.11	29.88
Scale:	1	* Manual P. T.	

FOB: PICK-UP

This Load: 29.88 TONS

Load No: 7

Shipped: 211.01 TONS

Weighmaster: Granite Construction Company
Deputy: Ryan Devries

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727622

9/8/2025

9:01:46AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB165SD SCB165SD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	100,140	45.42	50.07
Tare	40,560	18.40	20.28
Net	59,580	27.03	29.79
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 29.79 TONS

Load No: 6
Shipped: 181.13 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY .

Ticket No.

58727619

9/8/2025

8:49:50AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,820	44.37	48.91
Tare	37,340	16.94	18.67
Net	60,480	27.43	30.24
Scale:	1	* P.T.	

FOB: PICK-UP

This Load: 30.24 TONS

Load No: 5

Shipped: 151.34 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727618

9/8/2025

8:48:10AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB186SD SCARCELLA BROS 186SD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	99,540	45.15	49.77
Tare	39,920	18.11	19.96
Net	59,620	27.04	29.81
Scale:	1	* Manual P. T	

FOB: PICK-UP

This Load: 29.81 TONS

Load No: 4
Shipped: 121.10 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727617

9/8/2025

8:47:03AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,540	44.70	49.27
Tare	37,680	17.09	18.84
Net	60,860	27.61	30.43
Scale:	1	* Manual P.T.	

FOB: PICK-UP

This Load: 30.43 TONS

Load No: 3

Shipped: 91.29 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727612

9/8/2025

7:09:59AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB168BD SCARSELLA BROS 168BD

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	97,860	44.39	48.93
Tare	37,340	16.94	18.67
Net	60,520	27.45	30.26
Scale:	1	* P T	

FOB: PICK-UP

This Load: 30.26 TONS

Load No: 2

Shipped: 60.86 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

COPY

Ticket No.

58727611

9/8/2025

7:07:48AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB172BD SCARSELLA BROS 172BD

License: | |

Carrier:

Product - 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	98,880	44.85	49.44
Tare	37,680	17.09	18.84
Net	61,200	27.76	30.60
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.60 TONS

Load No: 1
Shipped: 30.60 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____

WARNING: THIS PRODUCT CONTAINS CRYSTALLINE SILICA (QUARTZ). CRYSTALLINE SILICA IS A COMMON NATURALLY OCCURRING MINERAL FOUND IN SAND AND ROCK. PROLONGED AND REPEATED BREATHING OF CRYSTALLINE SILICA DUST MAY CAUSE RESPIRATORY AND OTHER HEALTH PROBLEMS, INCLUDING LUNG DISEASE, SILICOSIS AND CANCER, WHICH MAY RESULT IN PERMANENT INJURY OR DEATH. BEFORE USING OR HANDLING THIS PRODUCT READ THE MATERIAL SAFETY DATA SHEET FOR MORE DETAILED INFORMATION INCLUDING INFORMATION ON APPROPRIATE RESPIRATORY PROTECTION. MSDS SHEETS AVAILABLE AT WWW.GRANITECONSTRUCTION.COM/MSDS OR BY CONTACTING YOUR LOCAL OFFICE.



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

ORIGINAL

Ticket No.

58727677

9/9/2025

8:57:25AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO# : 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product : 2206 SELECT BORROW

	<u>Pounds</u>	<u>Metric Tons</u>	<u>Tons</u>
Gross	105,500	47.85	52.75
Tare	43,200	19.60	21.60
Net	62,300	28.26	31.15
Scale: 1 * Manual P. T.			

FOB: PICK-UP

This Load: 31.15 TONS

Load No: 2

Shipped: 61.55 TONS

Weighmaster: Granite Construction Company

Deputy: Kiersa Howard

WEIGHMASTER CERTIFICATE

Accepted by: _____



Granite Falls
11423 Jordan Rd
Arlington, WA 98223
360-966-4970

ORIGINAL

Ticket No. **58727673**
9/9/2025 7:05:38AM

Customer: SCARSELLA BROS - EXEMPT
289502

Order ID: 341503
Job/PO#: 25025030-014

Cost Code

Location: SMITH ISLAND LEVEE LIFT
1871 ROSS AVENUE

Comments:

Weighmaster: Granite Construction Company
Deputy: Kiersa Howard

Vehicle: SCB111TT SCARSELLA BROS 111TT

License: | |

Carrier:

Product: 2206 SELECT BORROW

	Pounds	Metric Tons	Tons
Gross	104,000	47.17	52.00
Tare	43,200	19.60	21.60
Net	60,800	27.58	30.40
Scale: 1 * Manual Weight			

FOB: PICK-UP

This Load: 30.40 TONS

Load No: 1
Shipped: 30.40 TONS

WEIGHMASTER CERTIFICATE

Accepted by: _____