

Photo Documentation for Change Order 2

Project Name: Everett New Start Moisture Remediation

Prepared by: Accurate Assessment Environmental

Date: 11/30/24

Examples of new mold growth discovered after either baseboard, wallpaper, or GWB within the original protocol was removed. These examples are taken from rooms 218, 216, 217, and 212. Red chalk lines represent Atlas original cut lines. Blue chalk lines represent Atlas new cut lines after the baseboard has been removed.







